



NOTE: When mounting the actuator in this position it is necessary to remove the motor and motor adapter from the actuator and reinstall them on the opposite side of the actuator before completing the installation.

"East Mount"

AMERICAN ANTENNA INC.  
219-985-4000  
[www.americanantenna.com](http://www.americanantenna.com)

DRAWN: TJV  
DATE: 05/29/08 **6m Azimuth Range**

DWG. NO. **6-101074**